



The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE Lieutenant Governor

Representativ	es Present During the Inspection:	
Company	David Shaver Manager	
OGM	Karl Houskeeper Environmental Scientist III	

Inspection Report

Permit Number:	C0150032		
Inspection Type:	COMPLETE		
Inspection Date:	Wednesday, June 02, 2010		
Start Date/Time:	6/2/2010 7:00:00 AM		
End Date/Time:	6/2/2010 1:00:00 PM		
Last Inspection:	Wednesday, May 19, 2010		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Cloudy, Temp. 60 Deg. F. InspectionID Report Number: 2378

Types of Operations

Reprocessing

Accepted by: jhelfric

6/21/2010

Permitee: GENWAL RESOURCES INC Operator: GENWAL RESOURCES INC

Site: CRANDALL CANYON MINE

Address: PO BOX 1077, PRICE UT 84501

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

6,235.80	Total Permitted
27.15	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownershi	r
------------------	---

Other

✓ Federal ✓ Underground State ☐ Surface County Fee Processing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's	Signature:
mapector a	orginature.

Karl Houskeeper, Environmental Scientist III

Date

Wednesday, June 02, 2010

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0150032 Inspection Type: COMPLETE

Inspection Date: Wednesday, June 02, 2010

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark		✓	
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	V		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	V		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	V		✓	
4.d	Hydrologic Balance: Water Monitoring	✓			
4.e	Hydrologic Balance: Effluent Limitations	V		V	
5.	Explosives	✓	✓		
6.	Disposal of Excess Spoil, Fills, Benches	V	✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	~	✓		
8.	Noncoal Waste	✓		V	
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage	✓			
11.	Contemporaneous Reclamation	✓			
12.	Backfilling And Grading	✓			
13.	Revegetation	✓			
14.	Subsidence Control	✓			
15.	Cessation of Operations	✓			
16.a	Roads: Construction, Maintenance, Surfacing	✓			
16.b	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	V			
19.	AVS Check	V			
20.	Air Quality Permit	✓		✓	
21.	Bonding and Insurance	✓		V	
22.	Other	V			

Permit Number: C0150032 Inspection Type: COMPLETE

Inspection Date: Wednesday, June 02, 2010

Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

The DOGM permit is effective 05/13/2008 and expires 05/13/2013. Other documents include the following:

- ·Certificate of Insurance issued 06/01/2010 and terminates 06/01/2011.
- ·Reclamation agreement is dated April 1998 and is signed by both parties.
- UPDES permit UT000024368 effective 12/01/2005 and expires midnight 11/30/2010.
- ·Air Quality permit DAQE-AN0225003-03, issued 03/20/2003.
- ·SPCC Plan dated 11/02/2009.

2. Signs and Markers

The Mine ID sign is posted at the entrance to the permit area from the forest service road. The sign contains the name, permit ID #, address, and phone number of the operator.

The topsoil pile sign located on the topsoil pile left side of access road looking up canyon where access road first comes off main canyon road needs to be raised on the pole and secured in place.

Stream Buffer zone sign just below the topsoil pile and topsoil sign referenced above needs to be raised on pole and secured in place.

Both signs need to be visible.

3. Topsoil

Topsoil sign on topsoil pile left side looking up canyon where road first comes off main canyon road is at base of pole and needs to be raised and secured.

4.a Hydrologic Balance: Diversions

Cut in berm by culvert inlet adjacent to road grate at start of permit area to main facility needs to be repaired.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

First quarter 2010 sediment pond inspection was done on February 8, 2010.

4.c Hydrologic Balance: Other Sediment Control Measures

Silt fences (3) by stream buffer zone sign adjacent to topsoil pile referenced In item 3 need maintenance or replacement.

Silt fence at the base of the embankment of the sediment pond needs repair or replacement.

Permit Number: C0150032 Inspection Type: COMPLETE

Inspection Date: Wednesday, June 02, 2010 Page 4 of 4

4.e Hydrologic Balance: Effluent Limitations

Reviewed the discharge monitoring reports for January, February, March, and April 2010. January and February 2010 had exceeded iron parameters. The Division and DEQ are aware of this problem.

Noncoal Waste

Noncoal waste items identified in the previous inspection have been picked up and removed from the site.

20. Air Quality Permit

Approval Order DAQE-827-01 was modified on March 20, 2003. This modification allowed additional coal handling equipment (conveyors) for the South Crandall Portals. The new approval order, DAQE-AN0225003-03, was effective March 20, 2003.

21. Bonding and Insurance

nsurance is provided through Lexington Insurance Co. policy #047082728. The policy meets the minimum coverage requirements, has explosive coverage, contains the proper language in the notification clause, and shows the State of Utah as the certificate holder.